



## **Plastic Primer**

### **Description**

A 1K coating specifically designed to promote adhesion to various including AAS, PC/PET, PETP, PP-E, PP+E/P, PP/EPDM, TSOP.

It is quick drying and is ready for use therefore does not require thinning.

### **Application**

Ensure surfaces to be coated are dry, correctly prepared with p240 -p400 sandpaper and thoroughly degreased with panel wipe to remove all traces of contaminants.

Air cap: 1.0-1.2 mm Air pressure: 2.0bar or 30psi

1-2 light coats

### **Drying Times**

Flash off time, 5 minutes between coats

Recoat after 15 minutes at 20°C. Don't leave for more than 1 hour before over coating or the plastic primer will need scotching.